

Circuit: 3137X1 Nottingham		Area Work Center: Epping			Assessor: Tim C				Date:				
Tree #	Approved	DBH	Species	Pole	Property Address	Town	Risk	Additional Comments/ Traffic Control?	Customer Name	Contact Info	Permission Date	Assigned	Completed
1		32	maple	70/29-31	Stevens Hill Rd	Nottingham	trunk rot						
2		11	ash	70/29-31	Stevens Hill Rd	Nottingham	basal decay						
3		9	ash	70/29-31	Stevens Hill Rd	Nottingham	decay						
4		11	ash	70/29-31	Stevens Hill Rd	Nottingham	plow damage						
5		20	ash	875A/2-1	case rd	Nottingham	dead						
6		11	ash	875A/2-1	case rd	Nottingham	dead						
7		9	ash	875A/2-1	case rd	Nottingham	dead						
8		24	ash	875A/2-1	case rd	Nottingham	dead						
9		17	ash	859/3-4	Gile Rd	Nottingham	basal decay						
10		27	oak	859/4-5	Gile Rd	Nottingham	basal decay						
11		12	maple	859/4-5	Gile Rd	Nottingham	rot/decay						
12		16	maple	859/4-5	Gile Rd	Nottingham	rot/broken top						
13		23	maple	850F/10-11	Gile Rd	Nottingham	dead						